

UNIDADE DE ACOLHIMENTO

RACHADURA NA ENTRADA



VIDROS QUEBRADOS



PISO COM RACHADURAS



A photograph showing a close-up of a white door frame. The frame is in a state of disrepair, with a piece of yellow tape hanging from the top edge. The interior of the door is visible, showing a dark surface and a hinge on the left side. The overall scene suggests a need for maintenance or repair.

MARCO DA PORTA DETERIORADO

INSTALAÇÕES APARENTE



**BURACO QUE SERVIA DE ABRIGO
PARA RATOS.**



MOFO



BANHEIROS COM PROBLEMAS



PISO DESGASTADO



SACADA SEM REDE DE PROTEÇÃO



COLCHÕES DESMANCHANDO



ESCADA ESTREITA

